

DTA Consultants 10 Chestnut Walk Canvey Island Essex SS8 9JR	Asbestos Survey. Summary Public Conveniences @ <i>Unit 1. Magdalen Green. Old Road. Clacton. Essex</i> Date of Survey : June 2004
--	---

Suspect Materials, Sampled & subject to Analysis – Found not to contain asbestos

Description	Samp No	Asbestos found	Materials Assessment score
Texture coating to ceilings	1.1	None- Modern plaster based texture coating	NA
Flat Roof Covering	NA	None – Modern Material	NA

Suspect Materials, Sampled & Subject to Analysis – Found to contain asbestos

No Asbestos materials found in this property

Areas of No Access

All areas accessed as far as was safe to do so.

Conclusion

Brick Built building with a Flat Roof.
Plastic Water tank.
Foam Pipe insulation
Foam Cylinder Insulation.

No Asbestos materials have been identified. Materials contractors should be aware of are listed above although the materials found were non asbestos PPE & RPE should be worn when working on any materials where a Dust hazard is likely to arise.

Responsibility for any consequences arising from misinterpretation of the findings of this report will not be accepted by DTA Consultants.

Signed : **David Taylor**
(Principle DTA Consultants)